

Tutorial Santa-bead



Used colors:

Moretti:

black 064 (for the eyes)
white factorystringer and rod (for the beard, the hair, border of hat and white dot at the end of the hat)
Pink P260 (for the cheeks)
Red 424 of 428 (for the hat)

CIM :


703 Butter Pecan (for the face)

Preparation:

Pul some fat stringers from the pink, Butter pecan en black

Description:

Start making a small grapesized basebead using the Butter pecan and after it is ready add red glass at one side shaping it like a cone. Look at your bead and choose the side where you have the most Butter pecan showing and place two pink dots at the bottom side, marver them and melt them in. Look at the illustration on the right for referation where to place cheeks and eyes. Now we are going to place the eyes, as you can see they are about halfway between the top of the cheeks and the edge of the



hat. Spotheat this point, place your stringer into the hot glass and blow on the same spot to to solidify, so you can break the stringer to make your eye (be careful not to come to close and burn you lips!!!). Place the other eye the same way.

Use the factorystringer and place dots around the face at the edge of the hat and fill in the back of the head with white dots.



Now we are going to finish the hat. Start melting a small gather at the end of the red rod, and smear the glass in one movement from the topleft-side to the bottom rightside of the hat and let it protrude slightly. Do the same at the back of the hat but make sure it's attached to the startingpoint of the glass you just added for the frontpart. Make sure to melt everything well to attach it to the basebead and take some time to spotheat the startingpoints to merge them together. Heat the hatparts and make som wrinkles using a butterknife or something and add a white ball at the end of the hatshape.

Finish the santa by taking the Butter Pecan stringer and place a nice dot to form the nose.

Have fun using this tutorial!